

February 9, 1962
280

Mr. D. C. Zimmerman

Since word marks must be transmitted directly (no word separator) from the 1401 to hypertapes (7341-7641) a change was required in gate 02A2 I/O to provide the necessary circuitry. Several minor changes were also necessary to make the 1401 serial I/O adapter correspond more exactly to the IBM standard interface definition.

These changes will be installed on the 1401 hypertape system in Poughkeepsie prior to its entry into "B" test and will be released pending "B" test approval. All circuits concerned have been reserved.

John Pokoski

JP/ka

cc: Mr. J. S. Conzola
Mr. H. McCarthy
Mr. W. S. Schaffer
Mr. W. A. Wheeler